
BEFORE..WITH COVER

AFTER...WITHOUT COVER





BODY PAINT DAMAGE CAUSED BY FLUTTERING/LOOSE FITTING COVER...



